



Laser Warning Signs and Labels

Laboratories using class 2, 3, or 4 lasers are posted at each entry with the appropriate signage as indicated below. Post laboratories using class 3b and 4 lasers by the entranceways outside the facility with a lighted sign indicating the laser "ON" status to warn personnel of the presence of laser radiation.

All signs and labels must comply with ANSI Z 136.1 (2014) and the FDA/CDRH standards. Laser equipment labels indicate the laser class, wavelength, and the output power/energy of the laser system. The laser aperture (beam exit port) must be identified.

Class 2



Class 2M



Laboratory Safety

Class 3R



Class 3B



Class 4



Laser Instrument



Email radiation_safety@harvard.edu to send comments and suggestions to Radiation Safety Services.